



PL-259 Connector Installation Tool DXE-UT-80P

Patent Pending
DXE-UT-80P-INS Rev 1



This assembly tool allows simple threading of the PL-259 sleeve onto the vinyl jacket of RG-8/U, RG-213/U, LMR-400 and other similar size cables. First properly strip the coaxial cable with the **DXE-UT-8000** or **DXE-UT-8213** Cable Stripping Tool. Place the threaded sleeve of the PL-259 connector over the end of the coaxial cable. Start the coaxial cable end into the body of the connector and make sure all the strands of the center conductor of the cable are inserted into the center pin. Then, use this simple hand-gripped tool - forget about those pliers that scarred the connector and ripped off chunks of metal - and thread the connector body onto the stripped cable end. Tighten the tool until the PL-259 is fully seated on the coaxial cable. A visual guide at the end allows easy viewing of the cable center conductor for proper depth of installation. When the PL-259 is fully on the coaxial cable, remove it from the assembly. This tool allows a perfect and easy connector installation every time!



Properly prepare coaxial cable



Insert coaxial cable into PL-259



Use PL-259 Connector Installation Tool



Verify strands are fully into center pin



Remove tool and you're ready to solder



Martin Lynch & Sons Ltd
Outline House
73 Guildford Street
Chertsey
Surrey
KT16 9AS

UK
Tel: 01932 567 333
Fax: 01932 567 222
Outside UK
Tel: +44 1932 567 333
Fax: +44 1932 567 222